


SCFRM-GK10 PRODUCT INTRODUCTION



Red Dot Mounting Plate



Dowel Pins

RMSc/MGT

Red Dot Mounting Dowel Pinx4

RM/R/MOJ

Red Dot Mounting Dowel Pinx2


RM/R/MOJ

Red Dot Mounting Tapped Holes:
M3.5*12mm/16mm


RMSc/MGT

Red Dot Mounting Tapped Holes:
M3.5*12mm/16mm

A




Airsoft



M3*15 Flat Head Socket
Cap Screw

F



Firearm




M3*4 Flat Head Socket
Cap Screw x2

• Airsoft Pistol Mounting Method

* Ensure the cylindrical protrusion on the mounting block surface is inserted into the recessed slot at the bottom of the adapter plate.



① Insert Airsoft Mounting Block A into the bottom groove of the fixed Red Dot Base Plate.



M3*15 Flat Head
Socket Cap Screw

② Insert Airsoft Mounting Block A from below into the slide cover groove to connect with the Red Dot Base Plate on top of the slide cover.

③ Insert the M3*15 Flat Head Socket Cap Screw into the A1 insertion hole of the Red Dot Base Plate.

• Firearm Pistol Mounting Method

- ① Insert the Live Fire Mounting Block F sideways into the Picatinny rail slot.

